

F I G. 3




FIG. 4A






FIG. 4B



Jitter 12.6% Error rate: Measurement is impossible because of large asymmetry

F I G. 5



Jitter 13.4% Error rate: 4x10⁻⁶

FIG.6

